


502A 附件清单

名称	数量	备注
绝缘油实验仪主机	1 台	
电源线	1 根	
接地线	1 根	
油杯	1 个	
标准器具 (1mm, 2mm, 2.5mm, 4mm)	4 个	
电极罩	1 对	

<p>电极（蘑菇、平面和球面型）</p>	<p>3 对</p>	
<p>搅拌粒籽</p>	<p>2 个</p>	
<p>高压柱</p>	<p>1 对</p>	
<p>USB-RS232 转接线</p>	<p>1 根</p>	

打印纸	2 卷	
保险管 (5A/3A)	2 个/2 个	
说明书	1 份	——
光盘	1 张	——
检验报告	1 份	——
合格证	1 张	——